

State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd. Twinsburg, Ohio 44087

TELE: (330) 963-1200 **FAX:** (330) 487-0769 www.epa.state.oh.us

Ted Strickland, Governor Lee Fisher, Lieutenant Governor Chris Korleski, Director

April 6, 2009

RE: AKRON AIRDOCK 3II00203*AX

31100203*AX SUMMIT

Mr. Steve V. Vardavas Environmental, Safety and Health 1210 Massillon Road Akron, Ohio 44315-0001

Dear Mr. Vardavas:

On March 19, 2009 this writer conducted an inspection of the Akron Airdock. The purpose of the visit was to familiarize myself with the physical layout of the property. You represented Lockheed Martin during the inspection. The Akron Airdock when in operation manufactures airships for the military and government. As this facility does not generate process or non-process wastewater, storm water is the only regulated water discharge. The Airdock has recently undergone a multimillion dollar clean-up of the Airdock building, surrounding area, and storm sewers to remove PCB (Arochlor 1268) contamination. The source of the PCB was the deterioration of the roof and sides of the Airdock building

We reviewed the outside of the Airdock where you pointed out the work that has been done to remove PCBs from the Airdock structure as well as the surrounding pavement and soils. The internal outfalls which appear in the draft NPDES permit, 601, 602, and 603 were noted. Outfalls 601 and 602 combine at a point represented by 603. Outfall 603 eventually discharges to Haley's Ditch. The outlet of the storm sewer is identified in the NPDES permit as outfall 002.

I trust that the above is an accurate account of the inspection. If you should have any questions, feel free to contact this writer at (330) 963-1136.

Sincerely,

Philip P. Rhodes

Environmental Specialist II Division of Surface Water

The shal

PPR/mt

File: Industrial Permit Compliance