



Summit Soil & Water Conservation District

2795 Front Street, Suite D , Cuyahoga Falls, Ohio 44221

phone: 330.929.2871 fax: 330.929.2872

email: staff@summitswcd.org web: summitswcd.org

December 1, 2009

Mr. Matt Lascola, PE
GPD Associates
520 South Main Street
Akron, OH 44311

Subject: Site Inspection for Haley's Ditch Remediation/ Restoration – Akron, Ohio

Dear Mr. Lascola,

Joan Hug-Anderson, from Summit SWCD, made a site inspection for sediment and erosion control at the above-referenced site on November 30, 2009. Her comments follow:

STATUS OF THE SITE:

- The construction entrance on Wildon Ave. needs to have stone in place to prevent tracking mud off site.

Please ensure that perimeter checks are conducted to identify and correct problems with all erosion control practices.

If you have any questions, please contact this office at (330) 929-2871.

Sincerely,

Brian James, Supervisor
Summit SWCD

Pc: Jamie Krejsa, Riverworks 3781 Darrow Road, Stow, OH 44224
Andrew Davis, City of Akron Engineering
Daniel Joseph, Akron Public Utilities Bureau
Joe Schiavone, Summit County Building Standards
Steve Vardavas, Lockheed Martin
Mark Hurban, Arcadis - BBLES
File